


**ULINE** S-19274  
S-19275  
**PHASE CHANGE  
COOLING VEST**

1-800-295-5510  
uline.com



## USAGE AND CARE

### COOLING INSERT INSTRUCTIONS

1. Recharge the cooling inserts one of the following ways:
  - a. Place in a cooler of ice water for 10 minutes.
  - b. Place in a freezer for 15 minutes.
  - c. Refrigerate for 25 minutes.
  - d. Place near an air conditioner for 1-2 hours.
2. Insert the recharged cooling inserts in the inside vest pockets.
3. Adjust the hook-and-loop closures at the shoulders and around the body for a comfortable fit.

### COOLING INSERT CARE



**NOTE: DO NOT machine wash or machine dry.**

1. Wash by hand with mild detergent and warm water.
2. Dry with a paper towel or cloth.

### FABRIC VEST CARE

1. Machine wash in warm water.
2. Line dry.